

SSHS October Reporting to FM

LOCATION	Reported By	Room #	Date Documented	Description of Issue	Additional Information (as needed)	DEH Regulatory Requirement Section	Potential Demerits	Date Work Order Submitted	Work Order #	Current Status
SSHS	ADMIN	OUTSIDE CANOPY BUSING AREA	6/28/2016	SUPPLY	10 FT., 4 FT. GALVANIZED PIPE FOR DRAINAGE BY CANOPY, BUSING AREA	Section 6.19	2	6/28/2016	43321	PENDING
SSHS	TEACHER	JROTC	9/7/2016	HVAC	AC NOT WORKING	Section 7.21	2	9/7/2016	45389	PENDING
SSHS	TEACHER	212	9/8/2016	HVAC	AC NOT WORKING	Section 7.21	2	9/7/2016	45427	PENDING
SSHS	TEACHER	303	9/8/2016	HVAC	AC LEAKING BADLY INTO RM. 313	Section 7.21	2	9/8/2016	45453	PENDING
SSHS	TEACHER	302	10/7/2016	HVAC	AC LEAKING, NEED SERVICE	Section 7.21	2	10/7/2016	46041	PENDING
SSHS	TEACHER	306	10/14/2016	HVAC	AC LEAKING, NEED SERVICE	Section 7.21	2	10/14/2016	46176	PENDING
SSHS	TEACHER	SS BOOK ROOM	10/19/2016	CARPENTRY	ROOF LEAKING, NEEDS REPAIR	Section 6.13	2	10/19/2016	46237	PENDING
SSHS	TEACHER	216	10/19/2016	CARPENTRY	SECURE DROP CEILING IN HALLWAY	Section 6.13	2	10/19/2016	46239	PENDING
SSHS	TEACHER	ELEVATOR	10/19/2016	CARPENTRY	REPLACE CRACKED FLOOR TILES	Section 6.12	2	10/19/2016	46245	PENDING
SSHS	TEACHER	304	10/20/2016	CARPENTRY	REPAIR HOLE IN THE WALL	Section 6.13	2	10/20/2016	46265	PENDING
SSHS	TEACHER	303	10/20/2016	HVAC	AC LEAKING, NEED SERVICE	Section 7.21	2	10/20/2016	46269	PENDING
SSHS	TEACHER	306/112	11/3/2016	CARPENTRY	REPLACE CEILING TILES	Section 6.13	2	11/3/2016	46546	PENDING
SSHS	ADMIN	OFFICE/LOUNGE	11/3/2016	CARPENTRY	BUILD A WOODEN CRATE TO SURROUND BASE OF XEROX MACHINE	Section 5.7	4	11/3/2016	46547	PENDING
SSHS	TEACHER	SS BOOK ROOM	11/4/2016	CARPENTRY	REPAIR LEAKING ROOF	Section 6.13	2	11/4/2016	46557	PENDING
SSHS	STAFF	GIRL RR, CAFÉ	11/7/2016	CARPENTRY	REPLACE CEILING TILES	Section 6.13	2	11/7/2016	46597	PENDING
SSHS	TEACHER	305	11/14/2016	CARPENTRY	DOOR JAM NEEDS TO BE REPLACED	Section 6.14	2	11/14/2016	46667	PENDING
SSHS	TEACHER	103	11/14/2016	ELECTRICAL	RE WIRE LIGHT SWITCH FROM RM. 104 TO RM. 103	Section 8.23	2	11/14/2016	46698	PENDING
SSHS	TEACHER	212	11/17/2016	HVAC	AC STILL NOT WORKING	Section 7.21	2	11/17/2016	46800	PENDING
SSHS	TEACHER	307	11/22/2016	HVAC	AC NEEDS SERVICE	Section 7.21	2	11/22/2016	46883	PENDING
SSHS	STAFF	BOYS RR - CAFÉ	11/22/2016	PLUMBER	REMOUNT SINK IN RESTROOM	Section 11.29	2	11/22/2016	46884	PENDING
SSHS	STAFF	BOYS RR - CAFÉ	11/28/2016	CARPENTRY	REPAIR LAST STALL DOOR	Section 6.13	2	11/28/2016	46884	PENDING
SSHS	STAFF	211	11/28/2016	HVAC	AC NOT WORKING	Section 7.21	2	11/28/2016	46977	PENDING
SSHS	TEACHER	307	11/28/2016	HVAC	INVERTER BRAND AC NEEDS SERVICE	Section 6.21		11/28/2016	46981	PENDING
SSHS	TEACHER	309	11/29/2016	LOCKSMITH	REPAIR/REPLACE DOOR KNOB	Section 6.14	2	11/29/2016	47006	PENDING
SSHS	TEACHER	212/214	11/17/2016	HVAC	AC NOT WORKING NEEDS REPAIR	Section 7.21	2	11/17/2016	46800	PENDING
SSHS	TEACHER	116	11/30/2016	HVAC	AC NOT WORKING	Section 7.21	2	11/30/2016	47061	PENDING
SSHS	TEACHER	304	11/30/2016	HVAC	AC MAKING A LOUD NOISE	Section 7.21	2	11/30/2016	47066	PENDING
SSHS	TEACHER	116	12/1/2016	HVAC	AC NOT WORKING	Section 7.21	2	12/1/2016	47087	PENDING
SSHS	TEACHER	117	12/1/2016	HVAC	AC NOT WORKING	Section 7.21	2	12/1/2016	47089	PENDING
SSHS	TEACHER	120	12/1/2016	HVAC	AC NOT WORKING	Section 7.21	2	12/1/2016	47092	PENDING
SSHS	TEACHER	121	12/1/2016	HVAC	AC NOT WORKING	Section 7.21	2	12/1/2016	47093	PENDING
SSHS	TEACHER	112	12/1/2016	HVAC	AC NOT WORKING	Section 7.21	2	12/1/2016	47094	PENDING
SSHS	TEACHER	214	12/5/2016	HVAC	NEED TO ADJUST THERMOSTAT	Section 7.21		12/5/2016	47133	PENDING
SSHS	TEACHER	320	12/2/2016	HVAC	WESTING HOUSE INVERTER AC NEEDS TO BE SERVICED	Section 7.21		12/2/2016	47122	PENDING

SSHS October Reporting to FM

SSHS	TEACHER	320	12/5/2016	HVAC	WESTING HOUSE INVERTER AC NEEDS TO BE SERVICED	Section 6.21		12/5/2016	47134	PENDING
SSHS	TEACHER	BOYS RR - 108	12/5/2016	ELECTRICAL	REPLACE TWO LIGHT BULBS	Section 8.23	2	12/5/2016	47161	PENDING
SSHS	TEACHER	209	12/12/2016	CARPENTRY	REPAIR ROOF LEAK	Section 6.13	2	12/12/2016	47286	PENDING
SSHS	TEACHER	305	12/12/2016	CARPENTRY	LEAKING NEXT TO LIGHT FIXTURE. REPAIR ROOF LEAK	Section 6.13	2	12/12/2016	47287	PENDING
SSHS	TEACHER	301	12/14/2016	CARPENTRY	REPLACE WOOD COVERING IN FRONT	Section 6.13	2	12/14/2016	47358	PENDING
SSHS	TEACHER	114	12/22/2016	LOCKSMITH	DOORKNOB DOES NOT LOCK	Section 6.14	2	12/22/2016	47583	PENDING
SSHS	TEACHER	306	12/22/2016	CARPENTRY	REPAIR METAL COVERING HOLE OUTSIDE CLASS COMING LOOSE	Section 6.13	2	12/22/2016	47584	PENDING
SSHS	TEACHER	112	12/22/2016	HVAC	ADJUST AC THERMOSTAT- TOO COLD	Section 7.21	2	12/22/2016	47585	PENDING
SSHS	TEACHER	230	12/22/2016	HVAC	ADJUST AC THERMOSTAT- TOO COLD	Section 7.21	2	12/22/2016	47586	PENDING
SSHS	TEACHER	114	12/22/2016	HVAC	ADJUST AC THERMOSTAT- TOO COLD	Section 7.21	2	12/22/2016	47587	PENDING
SSHS	TEACHER	SS BOOK ROOM	12/23/2016	LOCKSMITH	REPLACE DOORKNOB/DEAD BOLT	Section 6.14	2	12/23/2016	47603	PENDING
SSHS	TEACHER	LOUNGE	12/23/2016	CARPENTRY	REPLACE CEILING TILE IN FRONT	Section 6.13	2	12/23/2016	47609	PENDING
SSHS	TEACHER	BOYS RR-108	12/23/2016	CARPENTRY	REPLACE STALLS	Section 6.13	2	12/23/2016	47611	PENDING
SSHS	TEACHER	SS BOOK ROOM	12/23/2016	CARPENTRY	REPAIR ROOF LEAK- LEAKING BAD	Section 6.13	2	12/23/2016	47612	PENDING
SSHS	ADMIN	313	1/4/2017	CARPENTRY	ROOF LEAK - CENTER OF ROOF	Section 6.13	2	1/4/2017	47795	PENDING
SSHS	ADMIN	313	1/4/2017	CARPENTRY	REPLACE FLOOR TILES DUE TO FLOOR LEAK	Section 6.12	2	1/4/2017	47796	PENDING
SSHS	ADMIN	313	1/4/2017	CARPENTRY	HOLE ON THE WALL ALONG CENTER WALL	Section 6.13	2	1/4/2017	47797	PENDING
SSHS	ADMIN	306	1/4/2017	CARPENTRY	ASSESS WOODEN CEILING- CRACK COMING THROUGH/BUBBLING	Section 6.13	2	1/4/2017	47798	PENDING
SSHS	ADMIN	312	1/4/2017	CARPENTRY	REPLACE WOODEN CEILING- LEAK/BUBBLING	Section 6.13	2	1/4/2017	47799	PENDING
SSHS	ADMIN	312	1/4/2017	CARPENTRY	REPLACE TILES	Section 6.12	2	1/4/2017	47800	PENDING
SSHS	ADMIN	304	1/4/2017	CARPENTRY	REPLACE/REPAIR CRACK ON WOODEN CEILING	Section 6.13	2	1/4/2017	47801	PENDING
SSHS	ADMIN	304	1/4/2017	ELECTRICAL	REPLACE OUTLET COVER	Section 6.19	2	1/4/2017	47802	PENDING
SSHS	ADMIN	304	1/4/2017	CARPENTRY	REPLACE TILES	Section 6.12	2	1/4/2017	47803	PENDING
SSHS	ADMIN	304	1/4/2017	CARPENTRY	REPLACE ROTTEN WOOD BY PLEXIGLASS	Section 6.13	2	1/4/2017	47804	PENDING
SSHS	ADMIN	304	1/4/2017	CARPENTRY	COVER BASE OF WALL TO MINIMIZE/STOP VECTOR FROM ENTERING- INSTALL BASEBOARDS; BASE OF WALLS ROTTING	Section 5.7		1/4/2017	47805	PENDING
SSHS	ADMIN	304	1/4/2017	CARPENTRY	CRACKED TILES BY ENTRANCE	Section 6.12	2	1/4/2017	47806	PENDING

SSHS October Reporting to FM

SSHS	ADMIN	304	1/4/2017	CARPENTRY	REPLACE DOOR CLOSURES (BROKEN)	Section 6.14	2	1/4/2017	47817	PENDING
SSHS	ADMIN	304	1/4/2017	CARPENTRY	REPLACE AWNING (WOODEN) OUTSIDE 304 ROOF	Section 6.19	2	1/4/2017	47818	PENDING
SSHS	ADMIN	305	1/4/2017	CARPENTRY	REPLACE TILES	Section 6.12	2	1/4/2017	47821	PENDING
SSHS	ADMIN	305	1/4/2017	CARPENTRY	HOLE UNDER THE AC/BACK OF WALL	Section 6.13	2	1/4/2017	47823	PENDING
SSHS	ADMIN	305	1/4/2017	CARPENTRY	REPAIR/INSTALL BASEBOARDS- VECTOR CONTROL	Section 5.7		1/4/2017	47824	PENDING
SSHS	ADMIN	305	1/4/2017	CARPENTRY	REPLACE PLEXIGLASS/WOOD BY DOORWAY ENTRANCE	Section 6.13	2	1/4/2017	47825	PENDING
SSHS	ADMIN	305	1/4/2017	CARPENTRY	REPAIR WOODEN CEILING CRACK	Section 6.13	2	1/4/2017	47827	PENDING
SSHS	ADMIN	305	1/4/2017	CARPENTRY	REMOVE/REPAIR PIPE FOR INTERNET LINE BY TEACHER DESK	Section 6.19	2	1/4/2017	47828	PENDING
SSHS	ADMIN	305	1/4/2017	CARPENTRY	SECURE WOODEN WALL BY CHALKBOARD	Section 6.13	2	1/4/2017	47831	PENDING
SSHS	ADMIN	305	1/4/2017	CARPENTRY	REPAIR WALL BY LIGHT SWITCH WHEN ENTERING THE CLASS	Section 6.13	2	1/4/2017	47832	PENDING
SSHS	ADMIN	305/306	1/4/2017	HVAC	RELOCATE AC DRAINAGE BETWEEN CLASSES- SLIP HAZARD	Section 6.21		1/4/2017	47852	PENDING
SSHS	ADMIN	306	1/4/2017	CARPENTRY	FIX OUTSIDE TRIP HAZARD-DRAINAGE- CHIPPED SIDEWALK CAUSES TRIP HAZARD BY WATER FOUNTAIN	Section 6.19	2	1/4/2017	47834	PENDING
SSHS	ADMIN	306	1/4/2017	CARPENTRY	INSTALL BASEBOARDS FOR VECTOR CONTROL/FIX BASE WALLS	Section 5.7		1/4/2017	47835	PENDING
SSHS	ADMIN	306	1/4/2017	CARPENTRY	ROOF LEAK -WATER STAINS ON CEILING	Section 6.13	2	1/4/2017	47837	PENDING
SSHS	ADMIN	307	1/4/2017	CARPENTRY	REPLACE ROTTEN FLOOR JAM/FLOORING	Section 6.14	2	1/4/2017	47838	PENDING
SSHS	ADMIN	309	1/4/2017	CARPENTRY	REPLACE WOODEN FLOORING	Section 6.12	2	1/4/2017	47839	PENDING
SSHS	ADMIN	309	1/4/2017	CARPENTRY	INSTALL BASEBOARDS/REPAIR WALLS FOR VECTOR CONTROL	Section 5.7		1/4/2017	47840	PENDING
SSHS	ADMIN	309	1/4/2017	CARPENTRY	REPAIR WALLS (TERMITE INFESTED)	Section 6.13	2	1/4/2017	47841	PENDING
SSHS	ADMIN	309	1/4/2017	CARPENTRY	REPLACE DOOR JAMS	Section 6.14	2	1/4/2017	47842	PENDING
SSHS	ADMIN	309	1/4/2017	CARPENTRY	REPLACE FLOOR TILES ALONG WALL	Section 6.12	2	1/4/2017	47843	PENDING
SSHS	ADMIN	309	1/4/2017	CARPENTRY	REPAIR HOLES ON WALL	Section 6.13	2	1/4/2017	47844	PENDING
SSHS	ADMIN	309	1/4/2017	CARPENTRY	MISSING DOOR SWEEPS	Section 6.14	2	1/4/2017	47845	PENDING
SSHS	ADMIN	309	1/4/2017	CARPENTRY	REPLACE WALL ALONG THE PANEL BOX	Section 6.13	2	1/4/2017	47846	PENDING
SSHS	ADMIN	314	1/4/2017	CARPENTRY	REPLACE CEILING TILES DUE TO WATER STAINS	Section 6.13	2	1/4/2017	47847	PENDING
SSHS	ADMIN	314	1/4/2017	CARPENTRY	ROOF LEAKS	Section 6.13	2	1/4/2017	47848	PENDING
SSHS	ADMIN	314	1/4/2017	CARPENTRY	REPLACE FLOOR TILES	Section 6.12	2	1/4/2017	47849	PENDING

SSHS October Reporting to FM

SSHS	ADMIN	314	1/4/2017	CARPENTRY	REPLACE WALL CHIPS BY DOOR ENTRANCE	Section 6.13	2	1/4/2017	47853	PENDING
SSHS	ADMIN	314	1/4/2017	CARPENTRY	HOLE ON WALL BY AC	Section 6.13	2	1/4/2017	47854	PENDING
SSHS	ADMIN	315	1/4/2017	CARPENTRY	NEED DOOR SWEEPS	Section 6.14	2	1/4/2017	47855	PENDING
SSHS	ADMIN	315	1/4/2017	CARPENTRY	REPLACE TILES ALONG FAR WALL	Section 6.12	2	1/4/2017	47857	PENDING
SSHS	ADMIN	315	1/4/2017	ELECTRICAL	REPLACE WIRING/PIPE METAL LOOSE	Section 6.19	2	1/4/2017	47858	PENDING
SSHS	ADMIN	317	1/4/2017	CARPENTRY	WOOD FALLING OFF ROOF AWNING (CORNER)	Section 6.13	2	1/4/2017	47859	PENDING
SSHS	ADMIN	318	1/4/2017	CARPENTRY	REPLACE TILES ALONG CHALKBOARD	Section 6.12	2	1/4/2017	47860	PENDING
SSHS	ADMIN	318	1/4/2017	CARPENTRY	REPAIR CORNER WALL BY ENTRANCE	Section 6.14	2	1/4/2017	47862	PENDING
SSHS	ADMIN	318	1/4/2017	CARPENTRY	INSTALL DOOR SWEEPS	Section 6.14	2	1/4/2017	47863	PENDING
SSHS	ADMIN	319	1/4/2017	CARPENTRY	INSTALL DOOR SWEEPS BOTH DOORS FOR VECTOR CONTROL	Section 6.14	2	1/4/22017	47864	PENDING
SSHS	ADMIN	319	1/4/2017	CARPENTRY	REPLACE FLOOR TILES	Section 6.12	2	1/4/2017	47864	PENDING
SSHS	ADMIN	319	1/4/2017	CARPENTRY	CEILING CRACK	Section 6.13	2	1/4/2017	47866	PENDING
SSHS	ADMIN	402	1/4/2017	CARPENTRY	ROOF LEAK CORNER OF ROOM NEAR AC	Section 6.13	2	1/4/2017	47867	PENDING
SSHS	ADMIN	404	1/4/2017	CARPENTRY	ROOF LEAK	Section 6.13	2	1/4/2017	47869	PENDING
SSHS	ADMIN	404	1/4/2017	CARPENTRY	CEILING TILES NEED REPLACEMENT	Section 6.13	2	1/4/2017	47870	PENDING
SSHS	ADMIN	404	1/4/2017	CARPENTRY	BROKEN TILES NEED REPLACEMENT (1EACH)	Section 6.12	2	1/4/2017	47872	PENDING
SSHS	ADMIN	404	1/4/2017	ELECTRICAL	REPLACE 5 BURNT LIGHT BULBS	Section 8.23	2	1/4/2017	47873	PENDING
SSHS	ADMIN	405	1/4/2017	CARPENTRY	ROOF LEAK	Section 6.13	2	1/4/2017	47874	PENDING
SSHS	ADMIN	405	1/4/2017	ELECTRICAL	REPLACE 3 BURNT LIGHT BULBS	Section 8.23	2	1/4/2017	47875	PENDING
SSHS	ADMIN	406	1/4/2017	ELECTRICAL	REPLACE 5 BURNT LIGHT BULBS	Section 8.23	2	1/4/2017	47876	PENDING
SSHS	ADMIN	407	1/4/2017	CARPENTRY	ROOF LEAK	Section 6.13	2	1/4/2017	47877	PENDING
SSHS	ADMIN	407	1/4/2017	CARPENTRY	REPLACE CEILING TILE #1	Section 6.13	2	1/4/2017	47878	PENDING
SSHS	ADMIN	407	1/4/2017	ELECTRICAL	REPLACE 2 BURNT LIGHT BULBS	Section 8.23	2	1/4/2017	47879	PENDING
SSHS	ADMIN	408	1/4/2017	CARPENTRY	ROOF LEAK	Section 6.13	2	1/4/2017	47881	PENDING
SSHS	ADMIN	408	1/4/2017	CARPENTRY	REPLACE 2 CEILING TILES	Section 6.13	2	1/4/2017	47882	PENDING
SSHS	ADMIN	408	1/4/2017	ELECTRICAL	REPLACE 2 BURNT LIGHT BULBS/DATA/VOICE OUTLET HANGING	Section 8.23	2	1/4/2017	47883	PENDING
SSHS	ADMIN	409	1/4/2017	ELECTRICAL	REPLACE 3 BURNT LIGHT BULBS	Section 8.23	2	1/4/2017	47884	PENDING
SSHS	ADMIN	409	1/4/2017	CARPENTRY	REPLACE CHIPPED TILES	Section 6.12	2	1/4/2017	478885	PENDING
SSHS	ADMIN	410	1/4/2017	ELECTRICAL	REPLACE 6 BURNT LIGHT BULBS	Section 6.19	2	1/4/2017	47886	PENDING
SSHS	ADMIN	410	1/4/2017	CARPENTRY	REPAIR HOLE ON DOOR	Section 6.14	2	1/4/2017	47887	PENDING
SSHS	ADMIN	411	1/4/2017	CARPENTRY	POSSIBLE LEAK: CONDENSATION IN LIGHT FIXTURES	Section 6.13	2	1/4/2017	47888	PENDING
SSHS	ADMIN	411	1/4/2017	ELECTRICAL	REPLACE 1 LIGHT BULB	Section 8.23	2	1/4/2017	47890	PENDING
SSHS	ADMIN	412	1/4/2017	ELECTRICAL	REPLACE 2 BURNT LIGHT BULBS	Section 8.23	2	1/4/2017	47891	PENDING
SSHS	ADMIN	201	1/4/2017	CARPENTRY	HOLE IN WALL BY BOARD AND PA SYSTEM	Section 6.13	2	1/4/2017	47892	PENDING

SSHS October Reporting to FM

SSHS	ADMIN	201	1/4/2017	ELECTRICAL	BROKEN OUTLET ON FLOOR BY TEACHER'S DESK	Section 6.19	2	1/4/2017	47893	PENDING
SSHS	ADMIN	202	1/4/2017	ELECTRICAL	REPLACE 1 BURNT LIGHT BULB BY TEACHER'S DESK	Section 8.23	2	1/4/2017	47894	PENDING
SSHS	ADMIN	202	1/4/2017	CARPENTRY	REPLACE TILES AROUND VENT	Section 6.13	2	1/4/2017	47895	PENDING
SSHS	ADMIN	203	1/4/2017	ELECTRICAL	REPLACE 3 BURNT LIGHT BULBS	Section 8.23	2	1/4/2017	47896	PENDING
SSHS	ADMIN	206	1/4/2017	CARPENTRY	DOOR KNOB NEED TO BE FIXED	Section 6.14	2	1/4/2017	47897	PENDING
SSHS	ADMIN	207	1/4/2017	ELECTRICAL	REPLACE 2 BURNT LIGHT BULBS	Section 8.23	2	1/4/2017	47899	PENDING
SSHS	ADMIN	210	1/4/2017	CARPENTRY	REPLACE SURROUNDING TILES BY VENT	Section 6.13	2	1/4/2017	47900	PENDING
SSHS	ADMIN	212	1/4/2017	HVAC	AC NOT WORKING	Section 7.21	2	1/4/2017	47902	PENDING
SSHS	ADMIN	214	1/4/2017	ELECTRICAL	REPLACE 2 BURNT LIGHT BULBS	Section 8.23	2	1/4/2017	47903	PENDING
SSHS	ADMIN	214	1/4/2017	CARPENTRY	REPLACE 2 BROKEN FLOOR TILES	Section 6.12	2	1/4/2017	47904	PENDING
SSHS	ADMIN	215	1/4/2017	ELECTRICAL	REPLACE 5 BURNT LIGHT BULBS	Section 8.23	2	1/4/2017	47906	PENDING
SSHS	ADMIN	217	1/4/2017	CARPENTRY	REPLACE SURROUNDING TILES BY VENT	Section 6.13	2	1/4/2017	47907	PENDING
SSHS	ADMIN	220	1/4/2017	CARPENTRY	REPLACE SURROUNDING TILES BY VENT	Section 6.13	2	1/4/2017	47908	PENDING
SSHS	ADMIN	221	1/4/2017	CARPENTRY	MISSING DOOR CLOSURE	Section 6.14	2	1/4/2017	47909	PENDING
SSHS	ADMIN	222	1/4/2017	ELECTRICAL	REPLACE 4 BURNT LIGHT BULBS	Section 8.23	2	1/4/2017	47910	PENDING
SSHS	ADMIN	222	1/4/2017	CARPENTRY	MISSING BROKEN DOOR CLOSURE	Section 6.14	2	1/4/2017	47911	PENDING
SSHS	ADMIN	223	1/4/2017	ELECTRICAL	REPLACE 2 BURNT LIGHT BULBS	Section 8.23	2	1/4/2017	47912	PENDING
SSHS	ADMIN	223	1/4/2017	CARPENTRY	REPLACE SURROUNDING TILES	Section 6.12	2	1/4/2017	47913	PENDING
SSHS	ADMIN	224	1/4/2017	CARPENTRY	EXIT MISSING DOOR CLOSURE	Section 6.14	2	1/4/2017	47914	PENDING
SSHS	ADMIN	225	1/4/2017	ELECTRICAL	REPLACE 1 BURNT LIGHT BULB	Section 8.23	2	1/4/2017	47915	PENDING
SSHS	ADMIN	226	1/4/2017	CARPENTRY	REPLACE SURROUNDING TILES BY VENT	Section 6.13	2	1/4/2017	47916	PENDING
SSHS	ADMIN	226	1/4/2017	CARPENTRY	DOOR CLOSURE MISSING/BROKEN	Section 6.14	2	1/4/2017	47917	PENDING
SSHS	ADMIN	227	1/4/2017	ELECTRICAL	REPLACE 1 BURNT LIGHT BULB	Section 8.23	2	1/4/2017	47918	PENDING
SSHS	ADMIN	227	1/4/2017	CARPENTRY	REPLACE SURROUNDING TILES BY VENT	Section 6.13	2	1/4/2017	47919	PENDING
SSHS	ADMIN	227	1/4/2017	CARPENTRY	REPLACE MISSING/BROKEN DOOR CLOSURE	Section 6.14	2	1/4/2017	47920	PENDING
SSHS	ADMIN	228	1/4/2017	CARPENTRY	REPLACE MISSING/BROKEN DOOR CLOSURE	Section 6.14	2	1/4/2017	47921	PENDING
SSHS	ADMIN	228	1/4/2017	CARPENTRY	REPLACE SURROUNDING TILES BY VENT	Section 6.13	2	1/4/2017	47922	PENDING
SSHS	ADMIN	229	1/4/2017	CARPENTRY	REPLACE SURROUNDING TILES BY VENT	Section 6.13	2	1/4/2017	47923	PENDING
SSHS	ADMIN	230	1/4/2017	CARPENTRY	REPLACE SURROUNDING TILES BY VENT	Section 6.13	2	1/4/2017	47924	PENDING
SSHS	ADMIN	231	1/4/2017	CARPENTRY	REPLACE SURROUNDING TILES BY VENT	Section 6.13	2	1/4/2017	47925	PENDING
SSHS	ADMIN	231	1/4/2017	CARPENTRY	MISSING/ BROKEN DOOR CLOSURE	Section 6.14	2	1/4/2017	47926	PENDING
SSHS	ADMIN	232	1/4/2017	CARPENTRY	MISSING/ BROKEN DOOR CLOSURE	Section 6.14	2	1/4/2017	47927	PENDING
SSHS	ADMIN	232	1/4/2017	CARPENTRY	REPLACE SURROUNDING TILES BY VENT	Section 6.13	2	1/4/2017	47928	PENDING
SSHS	ADMIN	313	1/4/2017	CARPENTRY	REPAIR HOLE ON WALL	Section 6.13	2	1/4/2017	47797	PENDING
SSHS	ADMIN	305	1/4/2017	CARPENTRY	REPAIR HOLE UNDER AC	Section 6.13	2	1/4/2017	47823	PENDING
SSHS	ADMIN	306	1/4/2017	ELECTRICAL	REPLACE 2 LIGHT BULBS	Section 8.23	2	1/4/2017	47930	PENDING
SSHS	ADMIN	401	1/4/2017	ELECTRICAL	REPLACE 2 LIGHT BULBS	Section 8.23	2	1/4/2017	47931	PENDING
SSHS	ADMIN	404	1/4/2017	ELECTRICAL	REPLACE 4 LIGHT BULBS	Section 8.23	2	1/4/2017	47932	PENDING
SSHS	ADMIN	409	1/4/2017	CARPENTRY	CHIPPED FLOOR TILES	Section 6.12	2	1/4/2017	47933	PENDING
SSHS	ADMIN	202	1/4/2017	CARPENTRY	REPLACE/REPAIR DOOR CLOSURE	Section 6.14	2	1/4/2017	47934	PENDING

SSHS October Reporting to FM

[illegible]